

# The Dustbane Way

## Cleaning a Manufacturing Facility



Cleaning a manufacturing facility starts with a simple program. Ask us about a custom program that will meet your individual needs. Here's our baseline recommendation.



### Sweeping Compound

Dustbane Sweeping Compound is used to clean and reduce airborne dust during sweeping and to ease the removal of dust and dirt on sealed and unsealed wood, concrete and metal floors. 100% biodegradable.

1



### Cleaner & Degreaser: Emerald

Because the machines used in manufacturing facilities often cause grease to build up on floors the choice of a good degreaser is very important. Emerald effectively cuts through grease, oil and heavily soiled surfaces, while having a reduced environmental impact. UL ECOLOGO® Certified.

- Dilute in cold water at a rate of 1:80 (cleaner)
- Dilute in cold water at a rate of 1:40 (degreaser)

2



### Hand Cleaner: Ultra Orange

Workers can get their hands dirty with a range of oils, grease and dirt. Ultra Orange is an industrial strength hand cleaner that can tackle any job, offering deep cleaning power while being gentle on the hands.

- Ready-to-use.
- Available in 4 L.

3



### Cleaner & Degreaser: Triple Action RTU

With busy schedules and the need for quick turnarounds, cleaning is not always possible. Triple Action RTU allows for quick cleaning and degreasing on the go.

- Ready-to-use.
- Available in 750 mL (RTU) & 5 L.

4



### Floor Sealer: Foundation

Foundation stops concrete dusting, improves stain resistance, increases abrasion and crush resistance, and makes the surface less susceptible to damage. Foundation achieves uncommon levels of durability and permanency for total sealer protection. APE and odour free. UL ECOLOGO® Certified.

- Two to three coats recommended.
- Available in 4 L & 20 L.

5



### Gladiator 664

Walk behind sweeper perfect for collecting small debris, with an industrial-strength body that will offer years of worry-free use..

- Quiet and not disruptive.
- Up to 3 hours of runtime
- 32" sweeping path.